

Cradle Point MBR1000 Supported Devices

These devices are supported on the latest version of firmware. Please ensure you are running the most recent firmware to ensure device compatibility.

(please visit <http://forums.rfwel.com> to view cards tested by RfWeL or our affiliates)
Updated 3/8/2010 (Contact us or visit <http://www.cradlepoint.com> for latest compatibility list)

3 (UK)

Huawei E156G

Alltel

Franklin CDU-550
Huawei EC168/C
Huawei EC228
Pantech UM175
UTStarcom UM150
(Pantech UM150)

AT&T

Option QuickSilver
Sierra Wireless 881U
Sierra Wireless 875U
USBConnect 881
USBConnect Mercury
USBConnect Lightning
ZTE MF636
Option GT Max 3.6 Express
Option GT Ultra Express
Blackberry 8310 (Curve)
Blackberry 9000 (Bold)
HP iPaq 910
Motorola RAZR v3xx
Motorola Q v9h
Samsung Blackjack
Samsung SGH-A707

B-Mobile (Japan)

ZTE MF626

Bell (Canada)

Novatel Wireless U760

Novatel Wireless MC998D

BridgeMAXX WiMAX

ZTE TU-25

Clear 4G

When using the Clear WiMAX network, the following Modem Firmware must be loaded onto the CradlePoint Router.

[Download Modem Firmware 5.2.206](#)

Clear USB Modem
Clear USB 4G Modem
Franklin U300 (3G and 4G)

Comcast High-Speed2Go

When using the Comcast High-Speed2Go network, the following Modem Firmware must be loaded onto the CradlePoint Router

[Download Modem Firmware 5.2.206](#)

Franklin CMU-300 (3G and 4G)
ZTE TU-25

Cricket

Calcomp a600
Pantech UM100
Pantech UMW185

E-Mobile (Japan)

D02HW
D11LC
D12LC
D21HW
D21LC
D22HW

nTelos

Franklin CDU-680
Kyocera KPC680

NTT Docomo (Japan)

LG L-02A

O2 (UK)

Sierra Wireless Compass 889U

Orange (UK)

Huawei E160E

Pioneer Cellular

Franklin CDU-680
Sierra Wireless USB 598
Sierra Wireless Aircard 402

Rogers (Canada)

Novatel MC950D
ZTE MF636 (Rocket Stick)
ZTE MF668 (Rocket Stick)
Novatel X950D

Softbank (Japan)

Softbank C01LC

Generic UMTS/GSM Devices

These devices were tested using the AT&T network in the United States and may or may not work with other UMTS/GSM carriers internationally.

Huawei E220
Huawei E160E - Orange Branded
Novatel MC930D
Novatel MC950D
Sierra Wireless 880U
Sierra Wireless 885U
(Compass 885)
ZTE MF626
Sierra Wireless 880E
Huawei E870
Huawei E870 - Orange Branded

Generic CDMA Devices

These devices were tested on CDMA networks that have approved these devices for use around the world and may or may not work with carriers that have approved them for

use on their networks. For specific information, please the carrier you are looking for usage approval of these devices on their network.

Huawei EC168C
Sierra Wireless USB 598
Sierra Wireless Aircard 402

Sprint

When using the Sprint WiMAX network, the following Modem Firmware must be loaded onto the CradlePoint Router

[Download Modem Firmware 5.2.206](#)

Franklin U300 3G/4G
Franklin U301 3G/4G
Franklin CDU-680
Novatel MiFi 2200
Novatel U720
Novatel U727
Novatel U760
Sierra Wireless 595U
Sierra Wireless Compass 597U
Sierra Wireless Compass 598U
Novatel EX720
Novatel C777
Sierra Wireless Aircard 402
Sierra Wireless 597E
Blackberry 8703e
Blackberry 8130
Blackberry 8330
Blackberry 8830
1HTC Touch
1HTC Mogul (6800)
1HTC Apache (6700)
LG Fusic LX-500
LG Muziq
Motorola KRZR
Motorola RAZR V3c
Motorola RAZR2
Motorola Q
Motorola Q9c
Palm Centro
Palm 700w
Palm 755p
Samsung A900
Samsung A900M
Samsung A920
Samsung ACE
Samsung i830
Samsung SPH-m520

Sanyo SCP-8400
Sanyo Katana
Sanyo Katana 2
Sanyo M1

Telus (Canada)

Sierra Wireless U306
Sierra Wireless 595U
Sierra Wireless 597U
Sierra Wireless 598U
Sierra Wireless 597E

Time Warner Cable Roadrunner Mobile 4G

When using the Roadrunner Mobile 4G network, the following Modem Firmware must be loaded onto the CradlePoint Router

[Download Modem Firmware 5.2.206](#)

Franklin CMU-300 (3G and 4G)
Franklin U301 (3G and 4G)
Motorola 25w100

T-Mobile

Huawei UMG-181
Option GE442

T-Mobile (UK)

ZTE MF637

Verizon

Novatel MiFi 2200
Novatel USB720
Novatel USB727
Novatel USB760
Sierra Wireless 595U
Pantech UM150
Pantech UM175
Pantech UMW190
Kyocera KPC680
Novatel V740
Novatel PC770
Blackberry 8703e
Blackberry 8130
Blackberry 8330
Blackberry 8830

Blackberry 9530 (Storm)
LG VX7200
LG VX8000
LG VX8300
Motorola RAZR V3c
Palm 700p
Palm 700w
Verizon XV6800

Virgin Mobile

Novatel MC760

Vodafone (UK)

Huawei K3565

1- *The user experience with devices running Windows Mobile is less robust than other phones and modems. Windows Mobile devices connected to either a PC or a CradlePoint router have exhibited erratic behavior while using data sharing capabilities. Issues include frequent disconnects for no apparent reason and remedies entail frequent rebooting the phone and or removing the phone's battery. This problem is not something that can be resolved by CradlePoint Technology and will need to be addressed by the phone manufacturer. Please refer to Cradlepoints [FAQ](#) section as well as the [release notes](#).*

Contact an RfWeL Wireless Support Specialist at www.rfwel.com if your card is not listed above. For a comprehensive list of accessories such as routers & antennas compatible with data modems from carriers around the world visit <http://www.rfwel.com/data/worldwide-data-carriers.php> or call us at +1.480.218.1877